




## **CNC Micro Machining Center - Model TC (4-position Automatic Tool changer)**





#### **4-Position Automatic Tool Changer**

\*Runs on 110V. Air connection required (Minimum 90psi)\*

### **Model CNC-TC Micro Machining Center – 4<sup>th</sup> Axis Ready**

#### **FOUR POSITION AUTOMATIC TOOL CHANGER.**

- 3 Axis: X—6" Y—4" Z—5-1/2"
- Travel Speed: 80 IPM (max.)
- Laptop computer
- Nema 23 Servo motors on each axis (155 oz/in peak torque)
- 4<sup>th</sup> axis wiring and integrated control module
- **Video Edge Finder**
- Safety enclosure
- Security lock
- Repeatability: .0002"
- 50k rpm spindle
- FlashCut G-Code software
- 350W brushless DC motor on the spindle
- Precision collet system (either a 2mm, 3mm, 1/8" or 4mm included)
- **Granite Surface Plate**
- 17" LCD Monitor

#### **Optional Equipment & Accessories:**

##### **4<sup>th</sup> Axis Unit**

Includes: Rotary table, 3-jaw chuck, right angle attachment, tail stock and T-slot table.

Prices & specifications are subject to change without notice.